



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program December 15, 2009

Reviewed: PTB

Mine Name: Cove Travertine 2	Permit Number: S/027/0092
Operator Name: Bob Steele	Inspection Date: May 27, 2009
Inspector(s): T Munson	Time: 12 noon
Other Participants: J Mansfield	Mine Status: ret

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$0.00

Purpose of Inspection: Site Inspection.

Inspection Summary:

The small site, approximately 5000 sq. ft., was regraded and left roughened. The surrounding area was rangeland in great condition. It should be noted that this permit actually is the same site as BEG Resources, S270061, Travertine Cove 2,3,4. This permit superceded Beg Resources' Permit # S270061 originally filed 6/23/1995 but that permit was never closed or transferred. Robert Steele was the claim holder under both permits.

This site has been retired. The reclamation looked good.

Photos were taken to document site conditions.

Conclusions and Recommendations:

This site has been retired. The reclamation looked good.

Inspector's Signature

TM:vs

cc: BLM Jerry_mansfield@inbox.com

O:\M027-Millard\S0270092-CoveTravertine\inspections\Insp-05272009.doc





Vegetation on site



Vegetation on site